


# Haw River near Benaja, N.C



**Study Reach.**--Section 4 is about 400 ft upstream from gage.

**Gage Location.**--Lat 36°16', long 79°34', on left bank 200 ft upstream from site of old High Rock Mill, 500 ft upstream from bridge on Secondary Road 2620, 0.5 mile upstream from Rockingham-Guilford County line, 6 miles downstream from Troublesome Creek, and 6 miles east of Benaja, Rockingham County.

**Drainage Area.**--168 sq mi.

**Gage Datum and Elevations of Reference Points.**--Not available.

**Stage, Discharge Measurements and Computed n-Values.**--Gage heights were 5.70 ft at gage; 6.09 ft at section 4. Peak discharges was 1,000 cfs on Dec. 29, 1958.



**Description of Channel.**--Bed is composed of coarse sand and a few outcrops. Banks on both sides are heavily lined with overhanging birch trees.

**Floods.**--

**Estimated n-Values using Cowan s Approach.--**

**Key words.--**